

# Notifiable incident

**Incident ID** [5531](#)

**Duty holder:** Shell Australia Pty Ltd  
**Facility/Activity:** Prelude FLNG  
**Facility type:** Floating liquefied natural gas facility

Incident details	
<b>Division</b>	Occupational Health and Safety
<b>Notification type</b>	Incident
<b>Incident date</b>	29/06/2018 12:00 AM (WST)
<b>Notification date</b>	29/06/2018 03:30 PM (WST)
<b>NOPSEMA response date</b>	05/07/2018 12:00 AM (WST)
<b>Received by</b>	[REDACTED]
<b>Nearest state</b>	WA
<b>Initial category type</b> <i>(based on notification)</i>	Dangerous Occurrence
<b>Initial category</b> <i>(based on notification)</i>	Damage to safety-critical equipment
<b>3 Day report received</b>	02/07/2018
<b>Final report received</b>	31/08/2018
<b>All required data received</b>	31/08/2018
<b>Final category type</b> <i>(based on final report)</i>	Dangerous Occurrence
<b>Final category</b> <i>(based on final report)</i>	Damage to safety-critical equipment
<b>Brief description</b>	OHS-DSCE-PFHE Room level instruments not meeting performance standards
<b>Location</b>	
<b>Subtype/s</b>	Facility integrity
<b>Summary</b> <i>(at notification)</i>	PFHE Room level instruments not meeting performance standards for SD001 Emergency Shutdown.

<b>Details</b> <i>(from final report)</i>	<p>PFHE Room level instruments not meeting performance standards for SD001 Emergency Shutdown.</p> <p>In addition to the standard bilge high level alarms, the Plate Frame Heat Exchanger (PFHE) Room bilge area has 4 High High Level switch units (720LSZ-4201A/B/C/D), one in each corner of the room, which activate an automatic shutdown and isolation of the SW2/CCW2 systems. These HH level switches are Safety Critical Elements with the functionality to detect room flooding in the PFHE room. They are part of a barrier for MAE-09: Sea/Cooling Water/Flooding of PFHE Room, and since the water systems are in use, this MAE is active. During the first yearly Preventative Maintenance test undertaken by Asset (previous testing completed in SHI yard by SHI) to ensure the integrity of the barrier, it was found that these level switches may not detect level in case a flooded room.</p> <p>The level switches are a tuning fork type, with the tuning forks located/ protected within a still well. To test the integrity of each unit, the still well was immersed in a bucket of water by lifting the bucket under the still well. When undertaking this test, the alarm did not activate. Further investigation found that the inside of the still well was dry including the switch forks. The still well that protects the switch has no vent to allow the air to escape when the water level rises, thus preventing the water to rising and coming in contact with the forks. This was found to be common across all 4 level switches. A further test was conducted to check the functionality of the switches by placing a hand inside the still well to active the level switches to ensure that the control loop worked correctly. This part of the test was successful and all alarms and functions in control room functioned satisfactory.</p> <p>A change has been implemented on the still wells to allow air to escape in case of immersion in water. The units are planned for re-test by 3/7 to confirm functionality.</p> <p>The temporary change implemented immediately after the incident (as described in the 3-day report) was tested as fully functional. Subsequently, the permanent change of drilling holes in the stilling wells was implemented and tested as fully functional.</p> <p>There are no other SCE tuning forks applications on Prelude whereby the tuning fork stilling well is installed in open air. All other tuning forks are installed within vessel stilling wells. Therefore, wider issues with these types of instruments are not expected.</p> <p>It has been verified that these PFHE room level instruments were tested during construction, however the method used was a dry method. No evidence has indicated a wider issue with testing of equipment, and the design for these instruments is unique for SHI.</p>
<b>Immediate cause/s</b>	SCE Level Switch units, 720LSZ-4201A/B/C/D, did not meet the performance criteria for SD001 Emergency Shutdown.
<b>Root cause/s</b>	ED - DESIGN - Design specs - problem not anticipated
<b>Root cause description</b>	Still wells for tuning forks had no vent to allow air to be displaced during immersion testing.

<b>Duty inspector recommendation</b>	
--------------------------------------	--

<b>Date</b>	15/08/2018
<b>Duty inspector</b>	
<b>Recommendation</b>	Do not conduct Major Investigation
<b>Reasoning</b>	Does not meet MI threshold based on information received
<b>Supporting considerations</b>	

<b>Major investigation decision</b>	
-------------------------------------	--

<b>Date</b>	15/08/2018
<b>Decision</b>	Do not conduct Major Investigation
<b>Reasoning</b>	Does not meet MI threshold based on information received
<b>Supporting considerations</b>	

<b>Non-major investigation review and recommendation</b>	
--	--

<b>Date</b>	15/08/2018
<b>Inspector</b>	
<b>Risk gap</b>	Moderate
<b>Type of standard</b>	Established
<b>Initial strategy</b>	Investigate

**Recommended follow up strategy**

<b>Recommended strategy</b>	Investigate
<b>Supporting considerations</b>	Flood detection system not operational. Initial conversation with the operator indicated a design issue creating an air lock which renders the sensors inoperable. Moderate risk gap - investigate.

**Non-major investigation decision**

<b>Date</b>	15/08/2018
<b>RoN</b>	
<b>RoN review result</b>	Agree with recommendation
<b>Strategy decision</b>	Investigate
<b>Supporting considerations</b>	

**Associated inspection**

<b>Inspection ID</b>	1772
----------------------	------