INTERNAL USE ONLY

Notifiable incident

Notification ID	<u>NTF11765</u>
Duty holder	Woodside Energy Ltd
Facility/Activity	Vincent
Nearest state	WA
Incident	OHS-DSCE - Failure of fire suppression system

Basic information provided at time of notification	
Notification type	Incident
Incident date	12/09/2022 05:00 PM (AWST)
Notification date	12/09/2022 05:30 PM (AWST)
NOPSEMA response date	12/09/2022 05:45 PM (AWST)
Received by	

Summary of information provided		
Brief descriptive title	OHS-DSCE - Failure of fire suppression system	
Incident location	Accommodation and amenities	
Subtype/s	Other	
Summary (provided at notification)	Failure of galley fire suppression system. Firing pin did not activate due to faulty O ring in CO2 firing system. Has been repaired and is functioning again. Did not comply with F19 performance standard. Had a 6 monthly check in March and had passed.	

Request permission to disturb the site		
Permission given	Not Applicable	
Permission given by		
Permission given on		

Initial spill and release amounts		
Gas (kg)		
Liquid (L)		
Release type		
More information		

Details of person providing information to NOPSEMA		
Full name		
Job title		

Initial notification category		
Initial category type (based on notification)	Dangerous Occurrence	
Initial category (based on notification)	OHS - damage to safety-critical equipment	

Running sheet

There are no running sheet entries for this notification

Decision	
Escalate to level 1	Yes
Inspector	
Escalated on	13/09/2022 11:53

Final notification category		
Final category type (based on final report)	Dangerous Occurrence	
Final category (based on final report)	OHS - damage to safety-critical equipment	

Immediate causes	
Details	Initial investigation has identified a perished "O"ring in the firing circuit.

15/09/2022
14/09/2022
16/09/2022
Brief description of incident During function testing of the galley wet chemical testing the firing pin failed to activate which was a failure of Performance standard F19.
Work or activity being undertaken at time of incident: 6 monthly F19 galley maintenance wet chemical system Inspection and function testing
What are the Internal Investigation Arrangements: Internal investigation in accordance with Woodside "Health Safety and
Environment Event Reporting, Investigating and Learning Procedure"
Action taken to make the work-site safe: Action taken Investigation and fault finding commenced to identify root cause and reinstate functionality. Details of any disturbance of the work site: Activities associated with investigating and rectifying the defect
Was an emergency response initiated? No Was anyone killed or injured? No Immediate action taken/intended, if any, to prevent recurrence of incident
Action Investigate and fault find potential root cause of failure. Responsible party Completion date 12-Sep-2022 Actual or Intended Actual Action Review SAP history to identify any previous issues with firing system. Responsible party Completion date 12-Sep-2022 Actual or Intended Actual

Final report		
Due date	12/10/2022	
Received date	20/09/2022	
Reviewed date	27/09/2022	
Reviewed by		

Additional details	Full Report:
provided by duty holder	Describe investigation in detail, including who conducted the investigation and in accordance with
	what standard/procedure -
	Investigation completed by in accordance with
	Woodside "Health Safety and Environment Event Reporting. During retune 6 monthly testing under
	WO 2200598997 the Wiltrading vendor was conducting the wet chemical dry fire of the system. When
	tested the mechanism for initiating the release functioned correctly but when the CO2 canister was
	released, the CO2 was released to atmosphere instead of being contained in the control tubing and
	initiating the firing pin. The Vendor investigated the CO2 firing mechanism and found an O-ring had
	perished causing the CO2 to be released to atmosphere. The O-ring was replaced and retested as per
	testing procedure which was successful.
	On Review of the Vendor maintenance program this O-ring was not part of any monthly or 6monthy
	inspection routines and was not listed as a material to be replaced while servicing.
	Actions to prevent recurrence of same or similar incident:
	Action 1 - O-ring replaced
	Responsible party -
	Completion date - 12-Sep-2022
	Actual or Intended - Actual
	Action 2 - Maintenance PRT updated to inspect O-ring during 6 monthly routine inspection and
	testing.
	Responsible party -
	Completion date - 15-Sep-2022
	Actual or Intended - Actual

Final spill and release amounts		
Gas (kg)	0.00	
Liquid (L)	0.00	
Release type		
More information		

Root causes	
Code	
Description	Has the investigation been completed? Yes Root Causes - Analysis Factor: EQ5-0 Equipment Tolerable Failure Comments - Investigation found O-ring in firing system is original and has never been replaced and not included in vendor service to replace

All data received	
Date	12/10/2022