

# Notifiable incident

<b>Notification ID</b>	<a href="#">NTF11777</a>
<b>Duty holder</b>	Woodside Energy Global Pty Ltd
<b>Facility/Activity</b>	Pyrenees
<b>Nearest state</b>	WA
<b>Incident</b>	OHS-DSCE - Lifeboat sprinkler system failure

Basic information provided at time of notification	
<b>Notification type</b>	Incident
<b>Incident date</b>	25/09/2022 11:00 AM (AWST)
<b>Notification date</b>	26/09/2022 06:36 AM (AWST)
<b>NOPSEMA response date</b>	26/09/2022 08:30 AM (AWST)
<b>Received by</b>	[REDACTED]

Summary of information provided	
<b>Brief descriptive title</b>	OHS-DSCE - Lifeboat sprinkler system failure
<b>Incident location</b>	
<b>Subtype/s</b>	
<b>Summary</b> <i>(provided at notification)</i>	Freefall lifeboat sprinkler system has failed to deliver water to nozzles. On inspection it was found that drive pulley separated from sprinkler pump shaft. Rest of lifeboat is functional. Repairs expected within 7 days.

Request permission to disturb the site	
<b>Permission given</b>	Yes
<b>Permission given by</b>	
<b>Permission given on</b>	

Initial spill and release amounts	
<b>Gas (kg)</b>	
<b>Liquid (L)</b>	
<b>Release type</b>	
<b>More information</b>	

Details of person providing information to NOPSEMA	
<b>Full name</b>	[REDACTED]
<b>Job title</b>	[REDACTED]

Initial notification category	
<b>Initial category type</b> <i>(based on notification)</i>	Dangerous Occurrence
<b>Initial category</b> <i>(based on notification)</i>	OHS - damage to safety-critical equipment

Running sheet
<i>There are no running sheet entries for this notification</i>

Decision	
Escalate to level 1	Yes
Inspector	██████████
Escalated on	27/09/2022 11:30

Final notification category	
Final category type <i>(based on final report)</i>	Dangerous Occurrence
Final category <i>(based on final report)</i>	OHS - damage to safety-critical equipment

Immediate causes	
Details	Internal face of drive pulley shows wear

Initial report	
Due date	28/09/2022
Received date	27/09/2022
Reviewed date	03/10/2022
Reviewed by	██████████
Additional details provided by duty holder	<p>Brief description of incident - A routine maintenance campaign was being undertaken on the Free Fall Lifeboat (FFLB) by the vendor and core crew. As part of the scope of work the sprinkler pump was changed out. During subsequent testing of the sprinkler system water was not delivered to the sprinkler nozzles. Upon investigation it was identified that the sprinkler pump drive pulley had separated from the sprinkler pump shaft. The FFLB is available for use to escape the facility in the event of an emergency however, the sprinkler system will not function.</p> <p>Work or activity being undertaken at time of incident - Freefall Lifeboat routine maintenance</p> <p>What are the internal investigation arrangements? - Investigate and repair – Case to Operate (Downgraded Situation)</p> <p>Was there any loss of containment of any fluid (liquid or gas)? - No</p> <p>Was NOPSEMA notified through the dedicated notification phone line? - Yes  Was permission given by a NOPSEMA inspector to interfere with the site? - No  Action taken - FFLB remains available for use without a working sprinkler system until repairs undertaken.</p> <p>Was an emergency response initiated? - No  Was anyone killed or injured? - No  Was there any serious damage? - No</p> <p>Details - Equipment damaged  Item 1 - FFLB sprinkler pump drive pulley  Extent of damage - Internal face of drive pulley shows wear  Will the equipment be shut down? - No – FFLB remains available</p> <p>Will the facility be shut down? - No</p> <p>Immediate action taken/intended, if any, to prevent recurrence of incident.  Action - Source replacement Sprinkler pump drive pulley  Responsible party - ██████████  Completion date - 3rd Oct 2022</p> <p>Are you attaching any documents? - No</p>

Final report	
Due date	25/10/2022
Received date	24/10/2022
Reviewed date	27/10/2022
Reviewed by	██████████
Additional details provided by duty holder	<p>Actions to prevent recurrence of same or similar incident:</p> <p>Action - Update Work Instruction 10000828884 - 3Y Replace FFLB Sprinkler Pump to state required torque values for assembly of the Pump Drive Hub securing nut - Responsible party - ██████████ -</p> <p>Completion date - Completed 24.10.2022</p>

Final spill and release amounts	
Gas (kg)	0.00
Liquid (L)	0.00
Release type	
More information	

Root causes	
Code	
Description	<p>Has the investigation been completed? Yes</p> <p>Root cause analysis</p> <p>Root cause 1</p> <p>Pump Drive Hub securing nut was over torqued, as the work instruction did not contain any guidance with respect to what torque setting is to be used.</p>

All data received	
Date	24/10/2022