

Additional Information

Immediate Causes

The Floorman was in the travel path of the stand.
Stand of drillpipe pulled out of the stump.

Incident Sub Type

Injury Pipehandling

Other Vessel Name

Incident Location

Drill Floor

Other Vessel Type

Person Involved

Contractor

Description

While running Drill Pipe from Derrick into the well with Pipe Handling System, a Floorman was inadvertently struck by a stand of Drill-Pipe during the connection process and was knocked backwards to the floor. Emergency Team called to the Drill Floor. Man assessed by the Medic and transported to the Hospital for further assessment. No visible injury except for some bruising. As recommended by Topside, IP will remain in observation overnight and likely to be disembarked on regular crew-change and sent to ashore for further assessment.

Spill and Release Amounts

Mass or Weight (kg)

Release Type

Volume (litres)

Equipment Involved (HC Form - Operator Analysis Part C)

Categories

Category

Actual Severity

Potential Severity

A315201







Duty Holder Reporting

3-day Report Due Date

3-day Report Received Date

Final Report Due Date

Final Report Received Date

Duty Holder Root Cause and Outcomes

Root Causes





Root Cause Descriptive

MRSP (Mandatory Rig Specific Procedure) not followed.
Lack of supervision.

Operator Investigation Outcomes

4 high

Write a more detailed procedure outlining each individual task step and each individual's responsibilities during this task. The procedure is to include all applicable requirements from H&S Manual, Field Operations Procedures manual and Performance and Operations Policies and Procedures manual. The procedure is to specify under which condition a person can be allowed to enter the Red Zone. The procedure is to be used by all crews while performing this operation. (RC 3.1, RC 3.2).

Racker operator to have a spotter on the rig floor at all times when operating the lower racker. (RC 3.2).

Ensure effective and lasting implementation of the "buddy system" as per H&S Manual section 2.24.

Toolpushers to print MRSPs and RRP for operations planned to take place during the day and to give a copy to the drillers for review during TBTs (RC 3.2)

NOPSEMA Investigation Outcome

Status



on 17/07/2013

NOPSEMA Investigation Outcomes

NOPSEMA Contact Details

Investigation Assigned To

▼

Investigation Team

Investigation ▼