

Notifiable incident

Incident ID [5347](#)

Duty holder: INPEX Operations Australia Pty Ltd
Facility/Activity: CPF Ichthys Explorer
Facility type: Other platform with accommodation facilities when drilling/workover facilities are not in commission

Incident details	
Division	Occupational Health and Safety
Notification type	Incident
Incident date	02/04/2018 06:40 PM (WST)
Notification date	02/04/2018 08:40 PM (WST)
NOPSEMA response date	02/04/2018 08:50 PM (WST)
Received by	[REDACTED]
Nearest state	WA
Initial category type <i>(based on notification)</i>	Dangerous Occurrence
Initial category <i>(based on notification)</i>	Unplanned event - implement emergency response plan
3 Day report received	05/04/2018
Final report received	05/04/2018
All required data received	05/04/2018
Final category type <i>(based on final report)</i>	Dangerous Occurrence
Final category <i>(based on final report)</i>	Unplanned event - implement emergency response plan
Brief description	OHS-UPE - GPA
Location	
Subtype/s	Alarm, Muster
Summary <i>(at notification)</i>	Unplanned GPA due to a Faulty manual Call Point.
Details <i>(from final report)</i>	Unplanned GPA due to a Faulty manual Call Point. Manual Call Point activated - GPA initiated. The CPF mustered as a result of the GPA. Investigation confirmed a false alarm due to a faulty MAC point.
Immediate cause/s	tbc
Root cause/s	
Root cause description	Water ingress into MAC point, caused by a loose-fitting EX plug and subsequent corrosion around the seal, caused the alarm to activate.

Duty inspector recommendation	
Date	02/04/2018
Duty inspector	[REDACTED]
Recommendation	Do not conduct Major Investigation
Reasoning	Does not meet MI threshold based on information received
Supporting considerations	

Major investigation decision	
Date	09/04/2018
Decision	Do not conduct Major Investigation
Reasoning	Does not meet MI threshold based on information received
Supporting considerations	

Non-major investigation review and recommendation	
Date	09/04/2018
Inspector	██████████
Risk gap	None
Type of standard	Established
Initial strategy	Inclusion in annual stats/data analysis

Recommended follow up strategy	
Recommended strategy	Inclusion in annual report stats / data analysis
Supporting considerations	<p>Possible same event or different events involving MAC points as notification 5345 - insufficient details. Awaiting 3 days report.</p> <p>Reviewed 3 days report (and final report) - The MAC point in question is located on lower deck riser balcony west (B-830-DMC-019) activated on 2 April 2018 . This is a separate event to that of 5345 (1 day apart). Both events has signs of water ingress into MAC enclosure. This event (latest) triggered a facility wide inspection of all MAC points (164) and to be completed by 3 May 2018.</p> <p>Water ingress into MAC point can result (have resulted) in false alarm. The 3rd of May completion date is ahead of RFSU confirmed by INPEX. ██████████</p>

Non-major investigation decision	
Date	09/04/2018
RoN	██████████
RoN review result	Agree with recommendation
Strategy decision	Inclusion in annual report stats / data analysis
Supporting considerations	

Associated inspection	
Inspection ID	