## Notifiable incident

Incident ID	<u>5593</u>	
Duty holder:	INPEX Operations Australia Pty Ltd	
Facility/Activity:	CPF Ichthys Explorer	
Facility type:Other platform with accommodation facilities when drilling/workover facilities are not commission		

Incident details	
Division	Occupational Health and Safety
Notification type	Incident
Incident date	23/09/2018 07:36 AM (WST)
Notification date	23/09/2018 04:50 PM (WST)
NOPSEMA response date	23/09/2018 04:55 PM (WST)
Received by	
Nearest state	WA
Initial category type (based on notification)	Dangerous Occurrence
Initial category (based on notification)	Unplanned event - implement emergency response plan
3 Day report received	26/09/2018
Final report received	26/09/2018
All required data received	26/09/2018
Final category type (based on final report)	Dangerous Occurrence
Final category (based on final report)	Unplanned event - implement emergency response plan
Brief description	OHS - UPE General Alarm and Muster
Location	
Subtype/s	Alarm, Muster
Summary (at notification)	False alarm form manual activation call point caused facility to go to general alarm & muster. Immediate cause : instrument fault
<b>Details</b> (from final report)	False alarm from manual activation call point caused facility to go to general alarm & muster. Immediate cause : instrument fault
Immediate cause/s	Instrument fault.
Root cause/s	ED - TOLERABLE FAILURE
Root cause description	Instrument fault

Duty inspector recommendation		
Date	23/09/2018	
Duty inspector		
Recommendation	Do not conduct Major Investigation Does not meet MI threshold based on information received	
Reasoning		
Supporting considerations	Waiting for 3 day report.	

lajor investigation decision	
Date	27/09/2018
Decision	Do not conduct Major Investigation
Reasoning	Does not meet MI threshold based on information received
Supporting considerations	

Non-major investigation review and recommendation		
Date	27/09/2018	
Inspector		
Risk gap	None	
Type of standard	Established	
Initial strategy	Inclusion in annual stats/data analysis	
Recommended follow up strategy		
Recommended strategy	Inclusion in annual report stats / data analysis	

 Reviewed INPEX initial (as well as final) report and confirmed that as false alarm from MAC point caused by faulty micro switch and not due to internal corrosion. The facility including ASV mustered
due to general alarm and as the per ER plan.
The CPF has previously mustered due to false alarm.

Non-major investigation decision	
Date	28/09/2018
RoN	
RoN review result	Agree with recommendation
Strategy decision	Inclusion in annual report stats / data analysis
Supporting considerations	Agreed.
	·

Associated inspection		
Inspection ID		