Regulatory Incident Notification Form 1.1

BHP Billiton Petroleum Pty Ltd Level 42, 152 158 St Georges Tce PO Box J668 Perth WA 6000 Australia	MITENTION: Duty Inspector ☑ NOPSA – 24hr Fax No. (08) 6461 7037 ☐ DolR Petroleum Division - 24hr Fax No. (08) 9222 38		
Total WA 6660 Additional	FROM:	Name:	
Tel +61 8 9338 4888	Position: Operations – Stybarrow Venture		
Fax +61 8 9338 4899	Date 11	/5 / 10	Time0302 No. Pages 1
Initial Notification of Incident:	Please be advis	ed that a report	able incident has occurred.
The facility name, site name	or location whe	re incident occu	rred: Stybarrow Venture
Name and business address Georges Tce, Perth, WA.	of employer wh	no controls work	site: BHP Billiton Petroleum - 152 - 158
3. Time 03:02 hrs and date 11/05/10 of incident;			
4. Names and contact details of any witnesses :			
Name of person submitting the Telephone number	nese details:		
6. Brief description of incident: 1st stage inlet PIT-0301A-06.	Gas release fro	om failure of flo	ow restrictor fitting on MPA Compressor
7. Work/activity being undertaken at time of incident; Routine operations			
8. Action taken, to make work-s disturbance of the work site: Con			tal damage, including details of any vn and isolated.
9. Was emergency response in	itiated: No.		
10. Name of employer of deceas	ed/injured perse	on(s) [if any and	d if different from answer in item 2]: N/A
11. Details of deceased/injured ptelephone number, occupation/jo			te of birth, sex, residential address and ils of job being undertaken; N/A
12. Day of shift and hour of shift (e.g. 5 th day of 7, 1 st hour of 12); N/A			
13. Estimated quantity and comp Hydrocarbon gas comprising r			r burned including known toxicity: kg.
14. Duration of escape; Inconclusive total time of leak: 50min total leak time.			
15. Location and weather conditions; Module A, Wind 266°, 3.4 knots.			
16. Identify equipment damaged interface point with mono flang		tent; Flow restr	ictor fitting snapped off cleanly at the
17. Will the plant be shutdown ar inspection is carried out on all			
			ce of incident; Machine shutdown and deer investigation and replacement.
19. Immediate cause analysis; E	xcessive vibra	tion / possible	over torque of fitting.
20. Root cause analysis and full	report; <i>Not app</i>	licable at this	stage
21. Actions to prevent recurrence Not applicable at this stage	e of incident wit	h responsible pa	arty and completion date;
Signature			Position:

ATTENTION: Duty Inspector