

Please check the following boxes if applicable to this report						
			Nil Incident Report: <input type="checkbox"/>	Final report for this activity: <input type="checkbox"/>		
Titleholder name:	Woodside	Titleholder business address:	11 Mount St Perth WA 6000	Title of environment plan for the activity:	Greater Western Flank 3 and Lambert Deep Drilling and Subsea Installation Environment Plan	
Activity type: (e.g. drilling, seismic, production)	Drilling	Month, Year:	November 2021	Facility name and type: (e.g. MODU, Seismic Vessel, FPSO)	Ocean Apex Moored MODU	
Contact person:	██████████	Email:	██████████@Woodside.com.au	Phone:	██████████	
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future	
28/11/2021 7:00	The black water line had become blocked and needed to be dealt with immediately. Therefore the overboard valve needed to be opened to release line blockage causing 1bbl of black water discharged into ocean.	Performance Standard 5.2 Page 220 of EP	None – no possible actions available	Not possible	Preventative Maintenance to flush black lines during tow	