

Please check the following boxes if applicable to this report			Nil Incident Report: <input type="checkbox"/>		Final report for this activity: <input type="checkbox"/>	
Titleholder name:	Woodside Energy Ltd	Titleholder business address:	Mia Yellagonga, 11 Mount St Perth WA 6000	Title of environment plan for the activity:	Ngujima-Yin Operations Environment Plan (Rev 13) [V0000AH0500]	
Activity type: (e.g. drilling, seismic, production)	Production	Month, Year:	January 2025	Facility name and type: (e.g. MODU, Seismic Vessel, FPSO)	Ngujima-Yin FPSO	
Contact person:	[REDACTED]	Email:	[REDACTED]@woodside.com	Phone:	[REDACTED]	
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future	
31 January 2025	<p>Hydraulic fluid weep of approximately 3-4 litres per hour identified during subsea campaign.</p> <p>Volume of Oceanic HW443 discharged to the marine environment is estimated to be approximately 4 litres x 12hrs = 48 litres.</p> <p>Oceanic HW443 is a water based, OCNS Group D product with substitution warning.</p>	EPO9: No unplanned release of hydrocarbons or chemicals to the marine environment	Post weep detection, the hydraulic line was isolated from a topside valve to stop the leak.	Subsea campaign to block the existing leak location subsea.	Leak is under investigation.	

Approved by:

[REDACTED]

[REDACTED]

Approved by:

[REDACTED]

[REDACTED]

Digitally signed by [REDACTED]
 DN: [REDACTED] c=AU,
 o=Woodside Energy, ou=Pluto,
 email=[REDACTED]@woodside.com
 Date: 2025.02.14 07:28:02
 +08'00'