



Esso Monthly Recordable Environmental Incidents

1-30 April 2025

Titleholder name:	Esso Australia Pty Ltd	Titleholder business address:	Level 9, 664 Collins Street Docklands, Victoria, 3008 GPO Box 400 Melbourne, Victoria 3001	Title of environment plan for the activity:	Various (see note below)
Activity type:	Various (see EPs listed below)	Month, Year:	April, 2025	Facility name and type:	Various (see note below)
Contact person:	██████████	Email:	██████████@exxonmobil.com	Phone:	██████████


Please find attached a copy of Esso's Gippsland Operations' recordable environmental incidents for the month of April 2025.

This report is submitted for the following Environment Plans:

- Gippsland Basin Geophysical and Geotechnical Investigations Environment Plan
- Bass Strait Environment Plan
- Jack-up Rig Plug and Abandonment Environment Plan

If no incidents are listed for any of the above EPs, it is taken to be equivalent to submitting a 'Nil' report.

Should you have any queries in relation to this letter, please contact ██████████ at ██████████@exxonmobil.com.

DocuSigned by:

 A40F3C8800354C2...

Offshore Risk, Environment and Regulatory Supervisor

Esso Australia Pty Ltd
 (for and on behalf of Esso Australia Resources Pty Ltd ABN 000 444 860)



Esso Monthly Recordable Environmental Incidents

1 – 30 April 2025

Environment Plan	Incident Date	Facility	ID	Performance outcome(s) and/or standard(s) breached	Incident Description	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future
Jack-up Rig Plug and Abandonment	20/4/2025	Mulloway -1	1600533	Breach of EPO (6) 'no spills to environment' (chemical).	<p>A sheen was observed on the sea surface below the Jack Up Rig.</p> <p>The source was found to be from a hydraulic hose fitting dripping from the starboard leg A cord rack chock cylinder.</p> <p>An estimated 0.1 L of hydraulic oil was released to sea.</p>	<p>To prevent further leaking, maintenance personnel isolated the affected hydraulics.</p> <p>The incident was reported to the [REDACTED]</p>	<p>The hydraulic fitting was inspected and replaced.</p> <p>The other two legs were inspected for similar leaks, with none identified.</p>	<p>Fluorescent marking pens are to be used after installation of hydraulic fittings in future, to highlight any movement of fittings during inspections.</p>
Bass Strait	25/4/2025	MLA	1601015	Breach of EPO (5) 'Limit impacts to habitat caused by dropped objects to a localised area'.	<p>During pack up activities, a welding blanket that had been positioned on a handrail was knocked and fell to sea.</p> <p>The blanket was approximately 2 m² in size.</p>	<p>The welding blanket was unable to be retrieved.</p> <p>The incident was reported to the [REDACTED].</p>		<p>The relevant team was advised that blankets are not to be hung on handrails and are instead to be secured immediately after use.</p> <p>Incident shared at platform daily meetings for broader awareness.</p>