Notifiable incident

Notification ID	NTF11967
Duty holder	Woodside Energy Ltd
Facility/Activity	CWLH OKHA FPSO
Nearest state	WA
Incident	OHS-DSCE - Damper Control Valve failed to meet performance standard during follow up testing related to NTF11961

Basic information provided at time of notification	
Notification type	Incident
Incident date	28/12/2022 10:30 PM (AWST)
Notification date	29/12/2022 01:10 PM (AWST)
NOPSEMA response date	29/12/2022 01:12 PM (AWST)
Received by	

Summary of information provided	
Brief descriptive title	OHS-DSCE - Damper Control Valve failed to meet performance standard during follow up testing related to NTF11961
Incident location	
Subtype/s	Valve failure
Summary (provided at notification)	Following on from the NTF11961 'OHS:DSCE - HVAC damper failed to meet performance standard during 3 monthly CFT testing' incident reported on 27/12 an action was to check all other valves for the same issue.
	All valves were checked and the Damper Control Valve was tested and found to be deteriorating. Then valves was switched to the closed position and will be replaced.
	No additional 3 day report will be issued as this will be reported in the NTF11961 3 and 30 day report.

Request permission to disturb the site	
Permission given	Not Applicable
Permission given by	
Permission given on	

Initial spill and release amounts	
Gas (kg)	
Liquid (L)	
Release type	
More information	

Details of person providing information to NOPSEMA	
Full name	
Job title	

Initial category type (based on notification)	Dangerous Occurrence
Initial category (based on notification)	OHS - damage to safety-critical equipment

Running sheet

There are no running sheet entries for this notification

Decision	
Escalate to level 1	Yes
Inspector	
Escalated on	12/01/2023 08:26

Final notification category	
Final category type (based on final report)	Dangerous Occurrence
Final category (based on final report)	OHS - damage to safety-critical equipment

Immediate causes Details

Initial report	
Due date	12/01/2023
Received date	28/12/2022
Reviewed date	13/01/2023
Reviewed by	
Additional details provided by duty holder	 Following on from the NTF11961 'OHS:DSCE - HVAC damper failed to meet performance standard during 3 monthly CFT testing' incident reported on 27/12 an action was to check all other valves for the same issue. All valves were checked and the Damper Control Valve was tested and found to be deteriorating. Then valves was switched to the closed position and will be replaced.
	No additional 3 day report will be issued as this will be reported in the NTF11961 3 and 30 day report.

Final report	
Due date	12/01/2023
Received date	28/12/2022
Reviewed date	
Reviewed by	
Additional details provided by duty holder	

Final spill and release amounts	
Gas (kg)	0.00
Liquid (L)	0.00
Release type	

More information	
Root causes	
Code	
Description	

All data received	
Date	12/01/2023