

Incident id	Year	Qtr	Incident Date	Notified date
2949	2012	3	7/09/2012 12:00	8/10/2012 12:00

Other receiver	Permission given to disturb site	Notifier name	Notifier job title	Notifier requested anonymity	Responded date
	Not Applicable		MV11		

Category type	Organisation	Regulatory object	Facility type	Incident type	Actual severity	Potential severity
Dangerous Occurrence	Modec Venture 11 B. V.	MODEC Venture 11	FPSO	Damage to safety-critical equipment	0	0

Summary title	Description	Subtypes	Gas kg	Liquid L
OHS - DSCE - pump gland seal failed	At 08:30 hours an unplanned muster was initiated via Zone 31 (Engine Room floor Starboard) fire detector in the Engine Room. All personnel muster and were accounted for.	Facility Integrity, Muster	0	0

Initial decision	Initial decision date	Initial decision reasons	Initial decision notes
No Further Action with the Information Currently Available	22/10/2012 14:35	No further action based on information received. Low potential.	

Critical decision issues	Critical decision options	Critical decision recommendations	Critical decision last action date	Critical decision reasons	Critical decision	Finalised

3 day report due date	3 day report received date	Final report due date	Final report received date
10/09/2012 12:00	8/10/2012 12:00	7/10/2012 12:00	8/10/2012 12:00

NOPSEMA investigation outcomes	Closed date	Root causes
Severity = 1 Low	17/07/2013 0:00	ED - DESIGN - Design specs - problem not anticipated