

Introduction

Date and time of actual event (A&DO/Environmental Incident/Complaint)

WST

(Note: Please enter all times in WST)

Date and time NOPSEMA notified

WST

Received By

Organisation and Facility

Organisation

Sedco Forex International Inc

Facility

Name	Type	
Jack Bates	MODU	View Issues

Summary of Information Provided

Brief Descriptive Title

Summary

A315199

While running Drill Pipe from Derrick into the well with Pipe Handling System, a Floorman was inadvertently struck by a stand of Drill-Pipe during the connection process and was knocked backwards to the floor. Emergency Team called to the Drill Floor. Man assessed by the Medic and transported to the Hospital for further assessment. No visible injury except for some bruising. As recommended by Topside, IP will remain in observation overnight and likely to be disembarked on regular crew-change and sent to ashore for further assessment.

Spill and Release Amounts

Mass or Weight (kg)

Volume (litres)

Release Type

Equipment Involved (HC Form - Operator Analysis Part C)

Request for Permission to Disturb the Site

Permission given

Not Applicable No Yes By

On

eg. dd/mm/yyyy

Details of Person providing information / notification to the Safety Authority

Name

Job Title

Preferred Contact #

Contact Email for Complaints Only

 Requested Anonymity

Address Line 1

Address Line 2

Address Line 3

City

State/Province/Region

Add Address Fields

N/a

Postal/ZIP Code

N/a

Country

Not Applicable

Categories

Category

Could have caused death or serious injury

Suggested Links

Links

Add Link