

Enforcement

Enforcement ID [673](#)

Duty holder: INPEX Operations Australia Pty Ltd
Facility/Activity: CPF Ichthys Explorer
Facility type: Other platform with accommodation facilities when drilling/workover facilities are not in commission

Incident details	
Division	Safety
Enforcement type	OHS improvement notice
Issue date	17/08/2017
Due date	16/10/2017
Days to respond	60
Date closed	18/10/2017
Issuing authority	[REDACTED]
Location	WA
Issues	Failure to implement a safe system of work. Incorrect cutting of 690V cable of temporary sea water lift pump B at cable transit. High potential multiple fatalities case. Multiple deficiencies found. Operator does not have cable identification verification procedure or work instruction for demolition work. No detailed tasks specific JHA & supervision. Section of risk assessment appended to ISSOW (PTW) found not completed. No confined entry contingency plan in place prior to work commencement.
Status	Closed - Pending Verification
Status reason	INPEX submitted IN 673 closeout dated 13/10/2017. A presentation was provided on 18/10.2017. Implementation of stated actions will be confirmed in the next planned inspection scheduled for Nov 2017. (NT) PI 1673 conducted in Nov 2017 and confirmed IN 637 closures (See PI 1673 report) (NT)
NOPSEMA contact	[REDACTED]
Enforcement team	A+I FPD
Links	Incident 4987, Inspection 1482