

[REDACTED]

From: [REDACTED]@Subsea7.com>
Sent: Wednesday, 26 February 2025 4:54 PM
To: [REDACTED]; [REDACTED]
Cc: [REDACTED]
Subject: Plastic saddle observed

Hi team,

As discussed with [REDACTED] this afternoon, we observed a plastic saddle wing float up when undertaking shear cutting subsea. We were not able to find it on the surface. Here is an attached photo for context.

From our discussions onshore between [REDACTED] and myself a few weeks ago, we agreed we would advise if this occurs again and we would re-assess reporting requirements and mitigation actions based on frequency. i.e. 2 or 3 saddles per 24 hour period.



Regards,

[REDACTED]

eMail [REDACTED]@subsea7.com
Mobile [REDACTED]

Subsea7, Westralia Square, Level 15, 141 St Georges Tce Perth, WA 6000, Australia

SAFETY | INTEGRITY | SUSTAINABILITY | PERFORMANCE | COLLABORATION | INNOVATION

Website www.subsea7.com

Please consider the environment – only print this e-mail if absolutely necessary

This message may contain confidential information which may also be legally privileged and is intended only for the use of the parties to whom it is addressed. If you are not an intended recipient you are hereby notified that any disclosure, copying, distribution or use of any information in this e-mail is strictly prohibited. If you receive this message in error please notify the sender by return e-mail and then destroy it. Further, we make every endeavour to keep our network free from viruses. However, you do need to verify that this e-mail and any attachments are free of viruses as we can take no responsibility for any computer viruses which might be transferred by way of this e-mail. All information and attachments remain the property of Subsea 7 and should be held as confidential.