

Woodside Energy Monthly Recordable Environment Incident Notification



Please check the following boxes if applicable to this report			Nil Incident Report: ☐		Final report for this activity: ☐	
Titleholder name:	Woodside Burrup Pty Ltd	Titleholder business address:	Mia Yellagonga, 11 Mount St Perth WA 6000	Title of environment plan for the activity:	Pluto Facility Operations Environment Plan [Rev 10]	
Activity type: (e.g. drilling, seismic, production)	Production	Month, Year:	March, 2025	Facility name and type: (e.g. MODU, Seismic Vessel, FPSO)	Pluto Alpha Platform	
Contact person:	[Redacted]	Email:	[Redacted]@woodside.com	Phone:	[Redacted]	
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future	
16 March 2025	Small volume of gas was found leaking through the gas supply braided hose inside a gas generator enclosure which could escalate to fire / explosion.	Yes, 5.8.5 Unplanned Hydrocarbon Release: Topsides Loss of Containment (MEE-03) PS 14.1 Integrity will be managed in accordance with SCE Management Procedure (Section 6.1.5.2) and SCE technical Performance Standard(s) to prevent environment risk related Damage to SCEs for: • P01 – Pressure Vessels • P02 – Heat Exchangers • P03 – Rotating Equipment • P08 – Piping Systems; to together: - provide minimum required mechanical integrity for identified SCE systems (piping, heat exchangers, rotating equipment, and pressure vessel) for operation within defined integrity limits so as to prevent a loss of containment that may result in a MEE.	None, no impact to environment	Starting of the generator was halted with the generator being isolated immediately.	Create hose data sheet and procure replacement hose. Survey of all hoses on generators of this type to determine if data sheets are available and if maintenance plan are in place to conduct planned inspections or replacement. Create maintenance plan for inspection replacement of fuel gas hose and other hoses identified during survey.	

Approved by: [Redacted] Approved by: [Redacted]
 [Redacted] (Apr 15, 2025 08:32 GMT+8)