Enforcement

| Enforcement ID | <u>707</u> |
|--------------------|--|
| Duty holder: | INPEX Operations Australia Pty Ltd |
| Facility/Activity: | CPF Ichthys Explorer |
| Facility type: | Other platform with accommodation facilities when drilling/workover facilities are not in commission |

| Incident details | |
|-------------------|---|
| Division | Safety |
| Enforcement type | OHS improvement notice |
| Issue date | 12/07/2018 |
| Due date | 11/08/2018 |
| Days to respond | 30 |
| Date closed | 30/07/2018 |
| Issuing authority | |
| Location | |
| Issues | Two workers received non-fatal electric shocks whilst working on an isolated 33kV high voltage interconnector cable installed between the CPF Ichthys Explorer facility and the Ichthys Venturer FPSO facility. The high voltage cable screen was not connected to earth in accordance with the Australian Standards. |
| Status | Closed |
| Status reason | Operator returned signed Improvement Notice form, dated 27 July 2018, together with: Covering letter Objective Ref: A622774, explaining notice closing actions as well as actions moving forward which are waiting on the operators findings from their investigation of the electric shock incident. Photos Objective Ref: A622771. The cable screens have been earthed and localised earth testing completed. Full earth testing will be performed following operators investigation report. |
| NOPSEMA contact | |
| Enforcement team | A+I FPD |
| Links | Incident 5468, Inspection 1821 |