

Please check the following boxes if applicable to this report			Nil Incident Report: <input type="checkbox"/>			Final report for this activity: <input type="checkbox"/>		
Titleholder name:	Woodside Energy Ltd	Titleholder business address:	Mia Yellagonga, 11 Mount St Perth WA 6000	Title of environment plan for the activity:	WA-34-L Pyxis Drilling and Subsea Installation Environment Plan XB0005GF1401780508			
Activity type: (e.g. drilling, seismic, production)	Drilling and Completions	Month, Year:	April 2025	Facility name and type: (e.g. MODU, Seismic Vessel, FPSO)	Valaris DPS-1 (MODU)			
Contact person:	[REDACTED]	Email:	[REDACTED]@woodside.com	Phone:	[REDACTED]			
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future			
06 April 2025	<p>At approximately 1220hrs the MMA Leeuwin offshore supply vessel (OSV) was brought alongside the DPS1 for cargo operations, without the Marine Fauna Observer (MFO) 30-min observation period for pygmy blue whales (PBW's). The MFO identified from the 'Deck Logbook' that the MMA Leeuwin was alongside without the observation period (upon attending the Bridge at 1400hrs).</p> <p>The omission of the 30-minute PBW observation period constitutes a breach of WA-34-L Pyxis Drilling and Subsea Environment Plan.</p>	<p>EPO 3 Undertake the Petroleum Activities Program in a manner that prevents injury to pygmy blue whales, or biologically significant behavioural disturbance.</p> <p>Control 3.3 Implement adaptive management procedure prior to supply vessel commencing approach to move alongside the MODU/ installation vessel within the Operational Area, during daylight hours. Adaptive management procedure to include:</p>	<p>Woodside representatives [REDACTED] and [REDACTED] set about investigating the events leading up to the incident</p>	<ol style="list-style-type: none"> 1. [REDACTED] to give the [REDACTED] a verbal notification of the vessel movements (while at PLA08). Goal being to provide opportunities for intervention 2. Bridge team to transcribe MFO and vessel communications from the 'working log' into the formal vessel daily logbook (which [REDACTED] then signs daily). 3. Implement and communicate updated <i>Valaris 500 Meter Zone Checklist</i>. Bridge team have added a section to the checklist which documents: <ul style="list-style-type: none"> Has the MFO been notified (must occur 45 min prior)? Has the MFO given permission to enter? 'All Clear' received from MFO? 4. <i>Marine Fauna Pre-watch Observation Process Prior to Resupply Vessel Approach</i> training slides for bridge crew updated; to reflect changes³ above 5. Environment Lessons Learned developed and shared with concurrent Australian drilling campaigns (<i>Transocean Equinox</i> and <i>Transocean Endurance</i>) 				



		<ul style="list-style-type: none">▪ Implement monitoring for pygmy blue whales 30 minutes prior to supply vessel commencing approach.▪ Proceed with move only when no pygmy blue whales have not been sighted within the limits of visibility.		