



Our ref: R006718: ID 0366: A215310
Your ref: Letter dated 17 Feb 12 & 1 Mar 12 & 2 April 2012
Contact: [redacted] (08) 6188 8719
Email: [redacted]@nopsema.gov.au

[redacted]
[redacted]
Enesco Australia Pty Ltd
10 Kings Park Road
WEST PERTH WA 6005

Dear [redacted]

ENFORCEMENT – FAILURE TO COMPLETE REMEDIAL ACTIONS TO MEET REVISED DATE STATED IN THE IMPROVEMENT NOTICE 366 / BREACH OF OPGGSA 2006 SCHEDULE 3 CLAUSE 78 (9)

I refer to Improvement Notice #366 issued to Enesco Australia Pty Ltd in relation to deficient electrical equipment in hazardous areas on the ENSCO 104 drilling rig. The extended date for the remedial work to be completed was 31 March 2012.

A letter from the ENSCO 104 [redacted], dated 2 April 2012, indicated that the remedial work was not completed on or before 31 March 2012. Furthermore, no written request was made by Enesco to NOPSEMA prior 31 March 2012 seeking further extension to the completion date.

Non-compliance with the Improvement Notice by the specified date constitutes an offence under Clause 78 (9) of Schedule 3 of the OPGGSA 2006. Given your commitment to have the work completed by 7 April 2012, NOPSEMA has decided not to take further action in relation to this matter.

You should note however, that this letter constitutes an enforcement action under NOPSEMA’s Enforcement Management Model and therefore will be taken into consideration when determining any future enforcement action for similar contraventions.

Should you have any queries regarding the above, please contact me on (08) 6188 8715.

Yours faithfully,

[redacted signature block]

Acting Manager – Assessment and Inspection

5 April 2012

cc: [redacted] (ENSCO 104), Enesco Australia Pty Ltd ([redacted]@enscoplc.com)
[redacted] Enesco Australia Pty Ltd ([redacted]@enscoplc.com)