From: @woodside.com.au>

**Sent:** Friday, 6 May 2011 2:32 PM

To: Cc:

Subject: RE: Improvement notice 0297 [SEC=UNCLASSIFIED]

Attachments: SWP-L07-3711050614140.pdf; SBC Addional Bracing 2.JPG; SBC

Additional Bracing 1.JPG; Aquip - Vibration Report - SBC.pdf

Afternoon

With reference to the below mentioned Improvement Notice 0297; please find attached evidence that corrective measures have been implemented, including the installation of an engineered bracing arrangement and subsequent infield vibration analysis of the small bore line referenced against the adjacent gas injection header.

Could you please confirm your acceptance of close out of Improvement Notice 0297, or conversely revert with any additional clarification required.

Best regards,



Woodside Energy Ltd.

Woodside Plaza 240 St Georges Terrace Perth WA 6000

Australia

M:

E: woodside.com.au

From:

Sent: Friday, 6 May 2011 1:40 PM

To:

Cc:

**Subject:** Improvement notice 0297 [SEC=UNCLASSIFIED]

Hi

The attached improvement notice is due on the 8th May. I have had no word on what action Woodside are taking in order to comply with the notice and progress.

Please can you provide an update.

Regards

OHS Inspector

National Offshore Petroleum Safety Authority (NOPSA)

Level 15, enex100 building 100 St Georges Tce Perth WA 6000

GPO Box 2568 Perth WA 6001

Ph: (08) 6461 7011 Fax: (08) 6461 7037 Mob

Email:

Web: www.nopsa.gov.au

A168017

Important: This message may contain confidential or legally privileged information. If you think it was sent to you by mistake, please immediately inform the sender, delete it from your system and do not disclose, copy or use the information contained in it. NOPSA does not guarantee that any message is secure, error-free or free of viruses or other unwanted or unexpected inclusions.

NOTICE: This email and any attachments are confidential. They may contain legally privileged information or copyright material. You must not read, copy, use or disclose them without authorisation. If you are not an intended recipient, please contact us at once by return email and then delete both messages and all attachments.



