

From: [REDACTED]
To: [REDACTED]
Subject: INPEX CPF Explorer - NTF12235 - Shaft Expelled During Seawater Filter Maintenance
Date: Thursday, 22 June 2023 11:26:45 AM

[REDACTED]

The investigation team into the above event have asked for an extension to the 30 day report due date. The investigation is nearing completion but it will take a few more weeks to finalise recommendations and complete review and approval. If they could extend until 14/7/23 that would be appreciated

Thanks

[REDACTED]

*ENEX 100 Building,
22/100 St Georges Terrace
Perth Western Australia 6000*

Tel [REDACTED]

Fax [REDACTED]

Mobile [REDACTED]

INPEX.com.au

The contents of this e-mail, including any attachments are the property of INPEX, are intended for use by the ordinary user of the e-mail address to which it was addressed and may also be privileged. If you are not the addressee of this e-mail you may not copy, forward, disclose or otherwise use it or any part of it in any form whatsoever. If you have received this e-mail in error please e-mail the sender by replying to this message. Emails sent or received may be monitored to ensure compliance with the law, regulation and/or INPEX policies.