

NOPSEMA Inspection – CPF Ichthys Explorer Facility

Document No: A925915

Safety Case:	CPF Ichthys Explorer Facility Safety Case (B070-AH-SCA-10000, Rev 12)
Operator:	INPEX Operations Australia Pty Ltd
Inspection dates	
Offshore:	22/05/2023 – 25/5/2023
Onshore:	Non-planned.
Facility:	CPF Ichthys Explorer
Prepared by:	██████████
NOPSEMA Inspection No:	2514
Issue Date:	25 May 2023

1. Inspection Team


The inspection team comprised the following personnel:


Lead inspector	██████████
Inspection Team	██████████

2. Scope

The following topics formed the scope of this inspection:


- Verification of commitments from previous recommendations.
- Consultation with Health & Safety Representatives and members of the workforce.








3. Observations/Findings

The following provides an overview of the observations and preliminary findings from the planned inspection.

Topic 1. – 	
Observations	Preliminary Findings










Topic 2. – 


Observations	Preliminary Findings
--------------	----------------------







Topic 3. – Notifications of Dangerous Occurrences	
Observations	Preliminary Findings






<p><u>NTF12235 – Shaft expelled during seawater filter maintenance.</u></p> <ul style="list-style-type: none"> High potential incident (major injury/single fatality). Currently under investigation by INPEX. No clear root cause at the time of the inspection. 	
<p>Meet with Health and Safety Representatives</p>	
<p>Observations</p>	<p>Preliminary Findings</p>





Verification of duty holder actions in response to recommendations and/or conclusions	
Observations	Preliminary Findings
	<div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: black; width: 100%; height: 15px; margin-bottom: 5px;"></div>
General OHS Observations	
Observations	Preliminary Findings



4. Issue of inspection report

The draft inspection report will be issued to the operator as soon as practicable. At the time the draft report is issued, the NOPSEMA inspectors will offer to discuss the findings of the draft report with the inspection team. There will be an opportunity for the duty holder to correct any factually incorrect information contained within the draft report. Following the receipt of any comments, NOPSEMA will finalise and issue the inspection report. When conclusions are raised in the report that identify current or potential future non-compliance, NOPSEMA may seek information to verify the operator's progress in addressing the conclusions by the agreed due date.

NOPSEMA is committed to continuous improvement of its regulatory practices. Personnel involved in a NOPSEMA Inspections may submit feedback on the inspection via email to feedback.inspection@nopsema.gov.au