

[REDACTED]

From: [REDACTED]@Subsea7.com>
Sent: Tuesday, 4 March 2025 3:54 PM
To: [REDACTED]
[REDACTED]
Subject: 250304 Plastic saddle dislodged
Attachments: IMG_6453.JPG

Hi all,

We have identified a plastic saddle detach during cut 21 at 1514hrs 4/3/25. Attached photo with the saddle coming apart. The cut was made approximately 0.5m from the plastic saddle with the shear cutters. We maintained visual presence on the surface but were unable to locate the saddle to recover. We will log this on our hazard register for tracking. Now that we have a better understanding of the effect from cutting and failure rate, the team will aim for at least 1m away from the saddle when a planned cut approaches it.

Kind Regards

[REDACTED]
Seven Sisters

eMail [REDACTED]@Subsea7.com



SAFETY | INTEGRITY | SUSTAINABILITY | PERFORMANCE | COLLABORATION | INNOVATION

Website www.subsea7.com

Please consider the environment – only print this e-mail if absolutely

This message may contain confidential information which may also be legally privileged and is intended only for the use of the parties to whom it is addressed. If you are not an intended recipient you are hereby notified that any disclosure, copying, distribution or use of any information in this e-mail is strictly prohibited. If you receive this message in error please notify the sender by return e-mail and then destroy it. Further, we make every endeavour to keep our network free from viruses. However, you do need to verify that this e-mail and any attachments are free of viruses as we can take no responsibility for any computer viruses which might be transferred by way of this e-mail. All information and attachments remain the property of Subsea 7 and should be held as confidential.