

Our Ref: Contact: Email: R007421: ID 0374: A211803 (08) 6188 8751 @nopsema.gov.au

Maersk Drilling Australia Pty Ltd Locked Bag 890 COMO WA 6952

Dear

## ENFORCEMENT – KOOMEY UNIT / BOP CONTROL AS-BUILT DRAWINGS – OPGGSA SCHEDULE 3, CLAUSE 9(2)(d) AND (f)

Thank you for your updated responses to NOPSA Recommendation and Follow-up List arising from the planned inspection of the Nan Hai VI conducted from 9 to 12 August 2011, received by NOPSEMA on 9 March 2012.

During this inspection the following recommendation was made:

Recommendation 595-10a

## Koomey Unit / BOP Control Drawings - As Built:

Review the findings made in the Inspection Report, Section 6.2.8.

 Ensure a legible as-built drawing set is made available at the facility for the Koomey unit and BOP control system (including hydraulic, electric and pneumatic schematics/drawings).

Note: Selected panel to BOP control loops will be used to verify the as-built drawings.

During the facility inspection conducted from 6 to 9 March 2012, it was noted that the above recommendation was still 'work in progress'. With respect to recommendation no. 595-10a, your response to effectively close out this recommendation by March 2012 has been noted.

You are reminded that under clause (9)(2)(d) and (f) of Schedule 3 of the Offshore Petroleum and Greenhouse Gas Storage Act 2006, Maersk Drilling Australia Pty Ltd is required to take all reasonably practical steps to implement and maintain systems of work at the facility that are safe and to also to provide members of the workforce with the information necessary for them to carry out their activities in a manner that does not affect the safety of persons at the facility.

Considering Maersk's previous commitments to close out this recommendation I request that you provide documented evidence that the above recommendation is effectively addressed and closed out by 16 July 2012.

Level 8 Alluvion, 58 Mounts Bay Road, Perth WA 6000 GPO Box 2568, Perth WA 6001 Australia t 08 6188 8700 f 08 6188 8737 Please note that this letter constitutes an enforcement action under NOPSEMA's Enforcement Management Model and therefore will be taken into consideration when determining any future enforcement action for similar contraventions.

If you have any questions regarding the above, please do not hesitate to contact OHS Inspector on (08) 6188 8751 or alternatively contact me on (08) 6188 8720.

Yours faithfully



**Lead OHS Inspector** 

16 March 2012