



NOPSEMA

Recordable Environmental Incident Monthly Report

Due Date: By the 15th day of the following month.

Send completed form to: submissions@nopsema.gov.au via secure file transfer at <https://securefile.nopsema.gov.au/filedrop/submissions>

Reference: Regulation 26B

Please check the following boxes if applicable to this report			Nil Incident Report: <input type="checkbox"/>		Final report for this activity: <input checked="" type="checkbox"/>	
Titleholder name:	Woodside Burrup PTY LTD (WBPL)	Titleholder business address:	240 St Georges Tce. Perth	Title of environment plan for the activity:	WA-34-L Drilling and Subsea Installation Activities Environment Plan	
Activity type: (e.g. drilling, seismic, production)	Subsea Installation	Month, Year:	February 2015	Facility name and type: (e.g. MODU, Seismic Vessel, FPSO)	Nor Australis	
Contact person:	[REDACTED]	Email:	[REDACTED]@woodside.com.au	Phone:	[REDACTED]	
Incident date	All material facts and circumstances (including release volumes to environment if applicable)	Performance outcome(s) and/or standard(s) breached	Action taken to avoid or mitigate any adverse environmental impacts of the incident	Corrective action taken, or proposed, to stop, control or remedy this incident	Action taken, or proposed, to prevent a similar incident occurring in future	
25.02.15	<p>First Priority Report: WELEV15020170</p> <p>During the installation of the flexible flowline there was a discharge observed.</p> <p>An estimated 50L of treated MEG was lost to the marine environment. The MEG was treated with 550ppm Hydrosure and 50ppm Clear Dye, which equates to approximately 0.025L and 0.0025L respectively.</p>	<p>EPO 18</p> <p>No minor spills greater than 10 L to the marine environment from deck & subsea actives during the Petroleum Activities Program.</p>	<p>The activity ceased and the flexible was returned to surface for rectification.</p>	<p>The equipment was recovered to deck and checked, it was discovered that there was no seal plate in between the termination head and the low pressure cap.</p> <p>The vessel returned to shore where a seal plate was inserted.</p>	26.02.15	



NOPSEMA

Recordable Environmental Incident -
Monthly Report

Note 1: As at 28 February 2014, amendments to the Offshore Petroleum and Greenhouse Gas Storage (Environment) Regulations changed from environmental performance objective to environmental performance outcome. If you are reporting against an EP accepted under the old Regulations please report against the environmental performance objective for that activity.

Note 2: This form may be submitted in conjunction with the 'Injuries and Fatalities – Monthly Summary Report' Form available at www.nopsema.gov.au

Approved By:

[Redacted signature]

Approved By

[Redacted signature]

[Redacted signature]

12/3/15

[Redacted signature]

12/3/15

Privacy Notice

NOPSEMA collects your contact details for the purpose of administering the OPGGSA and associated regulations. NOPSEMA will not use or disclose your personal information for any other purpose without your consent, unless it is required or authorised by law, or relates to NOPSEMA's enforcement activities. Your personal information may be disclosed to the following organisations, entities or individuals:

- individuals who make a request under the *Freedom of Information Act 1982*
- the Australian National Audit Office and other privately-appointed auditors
- NOPSEMA's legal advisors.

NOPSEMA may occasionally be required to disclose information to overseas recipients in order to discharge its functions or exercise its powers, or to perform its necessary business activities. Information about how you can access, or seek correction to, your personal information is contained in NOPSEMA's APP Privacy Policy at www.nopsema.gov.au/privacy. If you have an enquiry or a complaint about your privacy, please contact NOPSEMA's Privacy Contact Officer on 08 6188 8700 or by email at privacy@nopsema.gov.au.